Lab Comments -- 2nd Quarter 1999

2nd Quarter 1999 Page 1 of 19

ACKLEY

WELL 1

Lab No.: 9905287 no sample Canceled 7-16-99 SH

Lab No.: 9905287 site

WELL 2

Lab No.: 9905283 Diesel test cancelled due to possible in-house contamination. Client

Lab No.: 9905283 will recollect. sm 08/16/99

WELL 3

Lab No.: 9905284 Diesel test cancelled due to possible in-house contamination. Client

Lab No.: 9905284 will resample. sm 08/16/99

WELL 4

Lab No.: 9905288 Plugged by Layne-Western in 1995. Lab No.: 9905288 no sample Canceled 7-16-99 SH

WELL 5

Lab No.: 9905289 Capped in 1986-Geological survey using for groundwater contamination

Lab No.: 9905289 no sample Canceled 7-16-99 SH

WELL 7

Lab No.: 9905285 Client collected at well 7 instead of 1, 4, 5 or 6.

AKRON

WELL 3

Lab No.: 9905420 Well 3 was plugged in 1994.

Lab No.: 9905420 no sample Canceled 7-15-99 SH

WELL 5

Lab No.: 9905417 Well 5 was disconnected from the system in 1991 and was given to the

Lab No.: 9905417 Golf course for watering purposes only.

Lab No.: 9905417 Diesel test cancelled due to possible in-house contamination. Client

Lab No.: 9905417 will resample. sm 08/16/99

WELL 6

Lab No.: 9905418 Client sampled well 6 because well 3 was plugged.

ALBION

WELL 3

Lab No.: 9907463 Received liter bottle with a loose cap, 1/4 of sample leaked out.

ALDEN

WELL 1

Lab No.: 9905638 no sample Canceled 7-19-99 SH Lab No.: 9905638 Removed and capped in 1990.

ALGONA

WELL 1

Lab No.: 9903587 duplicate results. 6-24-99 KLP

AMANA

WELL 5

Lab No.: 9905292 ms/msd

Lab No.: 9905296 no sample Canceled 7-16-99 SH

2nd Quarter 1999 Page 2 of 19

Lab No.: 9905296 No sample?

ANAMOSA

WELL 1

Lab No.: 9903983 no sample Cancel 6-17-99 SH Lab No.: 9903983 Well #1 abandoned 7-20-94.

WELL 2

Lab No.: 9903984 no sample Cancel 6-17-99 SH Lab No.: 9903984 Well #2 abandoned 7-18-94.

ANAMOSA STATE PARK

WELL 1

Lab No.: 9903801 Wapsipinicon State Park

ANAMOSA STATE PENITENTIARY

WELL 1

Lab No.: 9903624 results per Sarah May. 6-24-99 KLP

ANDREW

WELL 1

Lab No.: 9904367 the earliest time 09:50.

Lab No.: 9904367 New Well

ARLINGTON

WELL 4

Lab No.: 9905203 Well 3 & Well 4

Lab No.: 9905203 Well 3 and Well 4 were collected and given one sample number. There

Lab No.: 9905203 well 4. Client will need to resample.

Lab No.: 9905203 Client needs to resample due to not enough sample to run analyses.

ATLANTIC

WELL 1

Lab No.: 9905256 Client sent in without sample abandoned?

Lab No.: 9905256 no sample Canceled 7-16-99 SH

WELL 12

Lab No.: 9905254 ms/msd

WELL 2

Lab No.: 9905257 no sample Canceled 7-16-99 SH

Lab No.: 9905257 Client sent in without sample abandoned?

WELL 3

Lab No.: 9905258 no sample Canceled 7-16-99 SH

Lab No.: 9905258 Client sent in without sample abandoned?

WELL 4

Lab No.: 9905259 Client sent in without sample abandoned?

Lab No.: 9905259 no sample Canceled 7-16-99 SH

AUBURN

WELL 4

Lab No.: 9905101 Client sampled well 4 instead of well 2 or 3.

WELL 5

Lab No.: 9905102 Client sampled well 5 instead of well 2 or 3.

2nd Quarter 1999 Page 3 of 19

BRIGHTON

WELL 1

Lab No.: 9905733 no sample Canceled 7-20-99 SH

Lab No.: 9905733 Well #1 wasw plugged in 1989 due to casing colapse and infiltration,

Lab No.: 9905733 was filled with bentonite.

WELL 2

Lab No.: 9905731 71999

BRITT

WELL 3

Lab No.: 9905440 Well 3 is not a closed well but has not been run for over 14 years.

Lab No.: 9905440 no sample Canceled 7-15-99 SH

Lab No.: 9905440 This well is not listed as a backup well and is very hard to draw Lab No.: 9905440 a sample from without shuting off some water customers. I will

Lab No.: 9905440 draw a sample if it is really feasible.

BUFFALO

WELL 1

Lab No.: 9903905 6-15-99 at 12:50.

WELL 2

Lab No.: 9903906 6-15-99 at 12:30.

BURLINGTON

WELL 3

Lab No.: 9905069 Sample was collected at well 3 instead of MISS R.

CASCADE

WELL 2

Lab No.: 9903812 Plugged July 28 1998

Lab No.: 9903812 no sample Cancel 6-15-99 SH

WELL 3

Lab No.: 9903813 no sample Cancel 6-15-99 SH

Lab No.: 9903813 Plugged March 17 1995

WELL 5

Lab No.: 9903810 New Well not on list.

CEDAR FALLS

WELL 1

Lab No.: 9903317 no sample

Lab No.: 9903317 This well was abandoned on 10-18-91.

Lab No.: 9903317 cancelled due to no sample. slm 9/15/99

WELL 10

Lab No.: 9903314 raw water

WELL 11

Lab No.: 9903315 This is a new well since 1993, it was not on the list from the DNR.

Lab No.: 9903315 Well location is New Green Hill Rd.

Lab No.: 9903315 raw water

WELL 2

Lab No.: 9903318 no sample

Lab No.: 9903318 Well #2 - Tagged out April 5 1990 due to Cedar Falls Utilities,

2nd Quarter 1999 Page 4 of 19

Lab No.: 9903318 Cancelled due to no sample. slm 9/15/99 Lab No.: 9903318 previous leakage from undergroud storage tank-Sampled frequently the Lab No.: 9903318 following 5 years - No BTEX found - Has not ran for last 2 years. Lab No.: 9903318 Well #2 will probably not be returned to active statues. Lab No.: 9903318 At the present time the water table is quite high, so contamination Lab No.: 9903318 from storage tank could be drawn into the well at this time. WELL 3 Lab No.: 9903310 raw water WELL 5 Lab No.: 9903319 no sample Lab No.: 9903319 Well #5 is also tagged out. Soft start motor starter is burned up, Lab No.: 9903319 Cancelled due to no sample. slm 9/15/99 Lab No.: 9903319 awaiting repairs. Will contact UHL when well is back in service. WFII 6 Lab No.: 9903311 raw water WELL 7 Lab No.: 9903312 raw water WELL 8 Lab No.: 9903313 raw water WELL 9 Lab No.: 9903320 Well #9 is currently tagged out for well Kehibilitation (sp). Lab No.: 9903320 Lab No.: 9903320 Trying to recase this well to hopefully reduce Nitrate concentration. Lab No.: 9903320 Cancelled due to no sample. slm 9/15/99 Lab No.: 9903320 Not sure when work will be completed, hopefully in a month. Currently Lab No.: 9903320 Well #9 is on emergency status, I can call when we get the well back Lab No.: 9903320 in use or if you want, call me at the above # if this is Lab No.: 9903320 unsatisfactory. 319-268-5335 Paul Mallinger

CEDAR RAPIDS

WELL SEM

Lab No.: 9906471 Seminole Well #6
Lab No.: 9906472 Seminole Well #7
Lab No.: 9906560 Seminole Well #4
Lab No.: 9906561 Seminole Well #8

CENTRAL CITY

WELL 3

Lab No.: 9905086 Client collected at SEP 03, not well 1.

CHARLES CITY

WELL 6

Lab No.: 9903490 Charles City Well #6 was abandoned & plugged 10-31-95.

Lab No.: 9903490 no sample

Lab No.: 9903490 Canceled 6-8-99 SH

Lab No.: 9903490 See DNR form 542-1226 attached.

CHARLOTTE

WELL 2

Lab No.: 9905271 Fire Station

2nd Quarter 1999 Page 5 of 19

WELL 3

Lab No.: 9905272 Fire Station

CLARENCE

WELL 4

Lab No.: 9905478 Client sampled well 4 instead of well 1.

CLEAR LAKE U METH CAMP

WELL 1

Lab No.: 9904999 office Lab No.: 9904999 MS & MSD

Lab No.: 9904999 BEDDIEMS cancelled due to MS lost during extraction. sm 07/15/99

COLESBURG

WELL 2

Lab No.: 9905966 Client did not collect from well 1.

WELL 4

Lab No.: 9905967 Client did not collect from well 1.

COLUMBUS JUNCTION

WELL 1

Lab No.: 9905280 Well 1 plugged 1989.

Lab No.: 9905280 no sample Canceled 7-16-99 SH

WELL 2

Lab No.: 9905281 no sample Canceled 7-16-99 SH

Lab No.: 9905281 Well 2 plugged 1989.

WELL 3

Lab No.: 9905282 Well 3 plugged 1989.

Lab No.: 9905282 no sample Canceled 7-16-99 SH

WELL 4

Lab No.: 9905277 Sample collected at well 4 instead of 1, 2, or 3.

Lab No.: 9905277 ms, msd

WELL 5

Lab No.: 9905278 Sample collected at well 5 instead of 1, 2, or 3.

COON RAPIDS

WELL 3

Lab No.: 9904602 Abandoned and plugged by Northway well and pump co. invoice dated

Lab No.: 9904602 no sample Canceled 6-30-99 SH

Lab No.: 9904602 7-13-92.

CORALVILLE

WELL 1

Lab No.: 9903528 duplicate results per Sarah May. 6-24-99 KLP

WELL 10

Lab No.: 9903532 Client crossed out well 4 and replaced with well 10.

CRESCO

WELL 1

Lab No.: 9903821 no sample Cancel SH 6-15-99

Lab No.: 9903821 Well 1 Plugged 06-20-94 See DNR form 542-1226

2nd Quarter 1999 Page 6 of 19

WELL 2

Lab No.: 9903820 Well 2 Plugged 10-31-94 See DNR form 542-1226

Lab No.: 9903820 no sample Cancel SH 6-15-99

WELL 4

Lab No.: 9903822 Well 4 Being repaired not in production.

Lab No.: 9903822 no sample Cancel 6-15-99 SH

DAKOTA CITY

WELL 2

Lab No.: 9904719 label 15:00 at well 2.

WELL 3

Lab No.: 9904720 label 15:00 at well 3.

DECORAH

WELL 4

Lab No.: 9903280 No Sample

Lab No.: 9903280 Well #4 has been plugged since the early 70's per client.

Lab No.: 9903280 Cancelled KLP 6-09-99

DELMAR

WELL 2

Lab No.: 9904893 no sample

Lab No.: 9904893 The well was not in service at this time.

DONNELLSON

WELL 4

Lab No.: 9907799 Well #4 was plugged in 1970. Lab No.: 9907799 no sample Canceled 9-14-99 SH

WELL 5

Lab No.: 9907800 Well #5 was capped in 1979, no pump. Lab No.: 9907800 no sample Canceled 9-14-99 SH

DOW CITY

WELL 1

Lab No.: 9905965 Well 1 abandoned.

Lab No.: 9905965 no sample Canceled SH 7-21-99

DOWS

WELL 4

Lab No.: 9905315 ms, msd

DUBUQUE TABLE MOUND

WELL 1

Lab No.: 9903445 Pump House

Lab No.: 9903445 Well 1 is tied to PWS #3100600 which is on the label; per phone with

Lab No.: 9903445 Mike Frederick. SH 6-4-99

WELL 2

Lab No.: 9903446 Pump House

Lab No.: 9903446 Well 2 is tied to PWS #3100610 which is on the label;per phone with

Lab No.: 9903446 Mike Frederick. SH 6-4-99

2nd Quarter 1999 Page 7 of 19

DUNLAP

WELL 1

Lab No.: 9905740 20 W Iowa St

WELL 2

Lab No.: 9905741 21 W lowa St

WELL 3

Lab No.: 9905742 512 N Hwy 30

DYERSVILLE

WELL 1

Lab No.: 9903973 no sample Cancel 6-17-99 SH

Lab No.: 9903973 Shawver Well Company plugged abandoned well 1 on 4-7-95.

WELL 3

Lab No.: 9903974 Shawver Well Company plugged abandoned well 1 on 5-6-98.

Lab No.: 9903974 no sample Cancel 6-17-99 SH

EAGLE GROVE

WELL 2

Lab No.: 9903309 no sample

Lab No.: 9903309 Client did not sample because well was given to A.G.P. and they

Lab No.: 9903309 Cancelled KLP 6-09-99
Lab No.: 9903309 plugged it several years ago.

EAST AMANA

WELL 2

Lab No.: 9905290 Sample collected at well 2 instead of well 1 or 24.

EDDYVILLE

WELL 2

Lab No.: 9903808 Well 2 was plugged in Dec. 1995 with disinfected sand.

Lab No.: 9903808 no sample Cancel SH 6-15-99

ELKADER

WELL 5

Lab No.: 9904727 Well out of service, start up unknown. Lab No.: 9904727 no sample Cancel 7-1-99 SH

EVANSDALE

WELL 1

Lab No.: 9904701 544 Grand Blvd

WELL 3

Lab No.: 9904702 544 Grand Blvd

WELL 4

Lab No.: 9904703 544 Grand Blvd

WELL 5

Lab No.: 9904704 400 Ann Street

Lab No.: 9904704 Client sampled well 5 instead of well 2.

FARMERSBURG

2nd Quarter 1999 Page 8 of 19

Lab No.: 9905458 well 1-1939

FARMINGTON

WELL 1

Lab No.: 9904713 062999

WELL 2

Lab No.: 9904714 062999

FAYETTE

WELL 1

Lab No.: 9904574 Well 1 Plugged 1992.

Lab No.: 9904574 no sample Canceled 6-28-99 SH

WELL 3

Lab No.: 9904386 The liter sample was received broken.

FORT DODGE

WELL 14

Lab No.: 9903499 Client did not send vials; per phone with John will send today. SH 6-8

Lab No.: 9903499 Received vials 6-9-99.

GARNAVILLO

WELL 1

Lab No.: 9904228 East well

WELL 2

Lab No.: 9904229 West Well

WELL 4

Lab No.: 9904231 There was another well that was abandone in the early 1970's. We have

Lab No.: 9904231 no sample Canceled 6-28-99 SH

Lab No.: 9904231 only two wells.

GARRISON

WELL 2

Lab No.: 9905173 no sample Canceled 7-12-99 SH

Lab No.: 9905173 Well 2 has been out of service for a long time and is being worked

Lab No.: 9905173 on right now. It has no pump.

GILMORE CITY

WELL 2

Lab No.: 9904716 504 East IA ave & 105 south B ave

WELL 3

Lab No.: 9904717 504 East IA ave & 105 south B ave

GLIDDEN

WELL 6

Lab No.: 9905971 Received one liter sample broken.

WELL 7

Lab No.: 9905973 Client sampled from well 7 instead of well 4.

GOODELL

WELL 1

Lab No.: 9905312 311 Broadway

2nd Quarter 1999 Page 9 of 19

WELL 2

Lab No.: 9905313 311 Broadway

GRAND MOUND

WELL 1

Lab No.: 9904984 615 Clinton

WELL 2

Lab No.: 9904985 615 Clinton

GRISWOLD

WELL 3

Lab No.: 9905071 MS & MSD

GUTHRIE CENTER

WELL 5

Lab No.: 9903601 on the quart jar.

WELL 6

Lab No.: 9903603 This well has been capped, but not plugged or pump and motor removed.

Lab No.: 9903603 No sample well plugged Cancel SH 6-9-99

HANLONTOWN

WELL 1

Lab No.: 9905729 Pump house

HAWARDEN

WELL 2

Lab No.: 9903407 The quart sample was broken when received.

WELL 4

Lab No.: 9903409 The quart sample was recieved broken.

WELL 8

Lab No.: 9903413 The quart sample was received broken.

WELL 9

Lab No.: 9903414 The quart QA sample was received broken. Lab No.: 9903583 Received one sample jar broken. SH 6-9-99

HAZLETON

WELL 3

Lab No.: 9906046 Client sampled from well 3 instead of well 4.

HIAWATHA

WELL 1

Lab No.: 9903513 This well was plugged & abandoned on 7-15-97 by Greiner well service.

Lab No.: 9903513 no sample

Lab No.: 9903513 SH 6-8-99 Canceled because of no sample.

WELL 2

Lab No.: 9903514 This well was plugged & abandoned on 7-18-97 by Greiner well service.

Lab No.: 9903514 no sample SH 6-8-99

WELL 3

Lab No.: 9903515 This well was plugged & abandoned with concrete July of 1983.

Lab No.: 9903515 no sample SH 6-8-99

2nd Quarter 1999 Page 10 of 19

HUDSON

WELL 1

Lab No.: 9904570 Capped off 11-1-83

Lab No.: 9904570 no sample Canceled 6-28-99 SH

WELL 3

Lab No.: 9904571 no sample Canceled 6-28-99 SH

Lab No.: 9904571 Capped off 11-1-83

WELL 4

Lab No.: 9904573 Capped off 11-1-83

Lab No.: 9904573 no sample Canceled 6-28-99 SH

WELL 5

Lab No.: 9904383 Backup

Lab No.: 9904572 Strickly backup, Started purchasing water from Waterloo water works

Lab No.: 9904572 no sample Canceled 6-28-99 SH

Lab No.: 9904572 in 1981.

HUMBOLDT

SPRING 1

Lab No.: 9903922 Spring 1 and 2 have a common reservoir so combined sampling only.

Lab No.: 9903922 Client called IDNR to explain the situation to Gail George.

INDEPENDENCE

WELL 3

Lab No.: 9905722 N.E. Park

WELL 4

Lab No.: 9905723 Light Plant

WELL 6

Lab No.: 9905724 S.W.

WELL 7

Lab No.: 9905725 N.W.

IOWA CITY

IOWA R

Lab No.: 9903205 Iowa River - Raw

WELL 1

Lab No.: 9903204 Jordan Well #1

IOWA CITY U OF I

IOWA R

Lab No.: 9903262 U of I Water Plant

U OF I WAT

Lab No.: 9903259 Cancel because MS & MSD do not require separate numbers. SH 6-3-99 Lab No.: 9903260 Cancel because MS & MSD samples do not require separate numbers.

Lab No.: 9903260 SH 6-3-99

WELL 1

Lab No.: 9903261 U of I Water Plant

IOWA FALLS

WELL ER1

Lab No.: 9903399 Elk Run #1 (Foster park)

2nd Quarter 1999 Page 11 of 19

WELL ER2

Lab No.: 9903400 Elk Run #2

WELL ER3

Lab No.: 9903401 Elk Run #3 Riverbend

Lab No.: 9903401 Collected QA at separate sites.

WELL PS1

Lab No.: 9903402 Pine ST #1

Lab No.: 9903402 Collected QA at separate sites.

WELL PS2

Lab No.: 9903403 Pine ST #2

WELL PS3

Lab No.: 9903404 Pine ST #3

JANESVILLE

WELL 2

Lab No.: 9904590 Well #2 has been plugged for about 3 years.

Lab No.: 9904590 no sample Canceled 6-30-99 SH

JESUP

WELL 1

Lab No.: 9905415 Well 1 has been plugged & capped on 2/96.

Lab No.: 9905415 no sample Canceled 7-15-99 SH

WELL 2

Lab No.: 9905411 time on the label 07:56.

WELL 3

Lab No.: 9905412 time on the label 08:44.

WELL 4

Lab No.: 9905413 time on the label 08:59.

KENSETT

WELL 1

Lab No.: 9906410 Community Center

WELL 2

Lab No.: 9906411 Fire Station

LA MOTTE

WELL 1

Lab No.: 9905441 1940-inactive

WELL 2

Lab No.: 9905442 1959-active

LA PORTE CITY

WELL 3

Lab No.: 9905952 abandoned.

LECLAIRE

WELL 3

Lab No.: 9903495 no sample

Lab No.: 9903495 Well 3 inactive abandoned & capped 1965.

Lab No.: 9903495 Canceled 6-8-99 SH

2nd Quarter 1999 Page 12 of 19

LIME SPRINGS

WELL 1

Lab No.: 9906111 Water Tower

WELL 2

Lab No.: 9906112 Water Tower

LISBON

WELL 1

Lab No.: 9905044 Tower

WELL 2

Lab No.: 9905045 Railroad

LOST NATION

WELL 1

Lab No.: 9905635 504 Broadway

WELL 2

Lab No.: 9905636 600 Main

LOW MOOR

WELL 1

Lab No.: 9906252 Well #1 Emergency use only.

LYNNVILLE

WELL 2

Lab No.: 9904323 no sample

Lab No.: 9904323 No sample, the well is not longer used because they are hooked up to

Lab No.: 9904323 canceled due to no sample. rd 6/24/99

Lab No.: 9904323 rural water.

WELL 3

Lab No.: 9904324 No sample, the well is not longer used because they are hooked up to

Lab No.: 9904324 no sample

Lab No.: 9904324 cancelled due to no sample. rd 6/24/99

Lab No.: 9904324 rural water.

MANCHESTER

WELL 4

Lab No.: 9903504 Entry Point 1

WELL 5

Lab No.: 9903505 Entry 2

WELL 7

Lab No.: 9903507 Entry Point 3

WELL 8

Lab No.: 9903508 Entry Point 4

MANLY

WELL 1

Lab No.: 9906109 no sample Canceled 7-27-99 SH
Lab No.: 9906109 Well disconnected and cemented shut.

WELL 3

Lab No.: 9906110 Well 3 is privately owned city dissconnected from system.

2nd Quarter 1999 Page 13 of 19

Lab No.: 9906110 no sample Canceled 7-27-99 SH

MARBLE ROCK

WELL 2

Lab No.: 9906248 no sample Canceled 7-28-99 SH

Lab No.: 9906248 Well 2 not used (disconnected) from system.

WELL 3

Lab No.: 9906249 no sample Canceled 7-28-99 SH

Lab No.: 9906249 Well 3 not used (disconnected) from system.

MARION

WELL 2

Lab No.: 9903463 9th Ave &2nd St.

WELL 3

Lab No.: 9903464 3050 5th Ave

WELL 5

Lab No.: 9903466 2351 31st

MARQUETTE

WELL 3

Lab No.: 9905750 earliest time is 10:25.

MARSHALLTOWN

WELL 10

Lab No.: 9903623 Client plugged this well in 1993. Lab No.: 9903623 no sample Cancel SH 6-9-99

WELL 12

Lab No.: 9903622 no sample SH 6-9-99 Lab No.: 9903622 Client has no well 12.

WELL 6

Lab No.: 9903593 Received two sample jars broken.

WELL 9

Lab No.: 9903596 another sample that was sent separately.

MASON CITY

WELL 16

Lab No.: 9905308 Sample from well 16 instead of 2nd well 12 as stated by IDNR.

WELL A3

Lab No.: 9905301 Client did not send in information sheet for this site. Information

Lab No.: 9905301 was taken from the label.

MEDIAPOLIS

WELL 1

Lab No.: 9905407 Facility did not sample wells 2, 4 and 6.

WELL 2

Lab No.: 9905482 Well 2 pladded in late 80's.
Lab No.: 9905482 no sample Canceled SH 7-15-99

WELL 3

Lab No.: 9905408 Facility did not sample wells 2, 4 and 6.

WELL 4

Lab No.: 9905480 Client did not sample wells 1, 3 or 5.

2nd Quarter 1999 Page 14 of 19

WELL 5

Lab No.: 9905409 Facility did not sample wells 2, 4 and 6.

WELL 6

Lab No.: 9905481 Client did not sample wells 1, 3 or 5.

MERRILL

WELL 2

Lab No.: 9905124 no sample Canceled 7-12-99 SH Lab No.: 9905124 Well 2 plugged per Bill Merchant.

WELL 3

Lab No.: 9905125 no sample Canceled 7-12-99 SH Lab No.: 9905125 Well 3 plugged per Bill Merchant.

MILES

WELL 2

Lab No.: 9904994 MS & MSD

MONONA

WELL 1

Lab No.: 9904249 Well 1 was plugged and discontinued in 1991. It had been used as a

Lab No.: 9904249 no sample Canceled 6-28-99 SH

Lab No.: 9904249 Stand-by well, to that point, and we decided it wasn't needed when

Lab No.: 9904249 we redid the well house.

MONTICELLO

WELL 1

Lab No.: 9903904 no sample Cancel SH 6-16-99
Lab No.: 9903904 East well #1 does not exist anymore.

WELL 2

Lab No.: 9903900 South Well

WELL 3

Lab No.: 9903901 West well

WELL 4

Lab No.: 9903902 North well

MOUNT PLEASANT

WELL 3

Lab No.: 9905106 Well 3 was plugged and abandoned on 1-18-95.

Lab No.: 9905106 no sample Canceled 7-12-99 SH

MOUNT VERNON

WELL 1

Lab No.: 9905823 Well 1 abandoned.

Lab No.: 9905823 No Sample

Lab No.: 9905823 Cancel 8/17/99 tml

NORA SPRINGS

WELL 1

Lab No.: 9903980 no sample Cancel 6-17-99 SH

Lab No.: 9903980 Well #1 is plugged.

2nd Quarter 1999 Page 15 of 19

Lab No.: 9905002 Well #3 plugged 7-20-98.

Lab No.: 9905002 no sample Canceled 7-12-99 SH

NORTHWOOD

WELL NOR

Lab No.: 9904996 North Well

WELL SOU

Lab No.: 9904997 South Well

OELWEIN

WELL 70

Lab No.: 9903304 no sample

Lab No.: 9903304 This well was filled with rock and capped with cement in April of 1985 Lab No.: 9903304 Cancelled-no sample received-well was plugged. KLP 6-08-99

OSAGE

WELL 2

Lab No.: 9904709 earliest time is 10:02.

WELL 4

Lab No.: 9904710 earliest time is 10:21.

WELL 5

Lab No.: 9904711 earliest time is 09:29.

PEOSTA

WELL 1

Lab No.: 9905563 Lost Canyon Mobile Home Park

PERRY

WELL 11

Lab No.: 9903972 Perry's Well #11 has been scheduled to be abandoned this summer.

Lab No.: 9903972 no sample Cancel 6-17-99 SH

WELL 8

Lab No.: 9903971 Perry's Well #8 was abandoned in November of 1991.

Lab No.: 9903971 no sample Cancel 6-17-99 SH

POSTVILLE

WELL 5

Lab No.: 9904255 Received samples from Well 5 instead of Well 1.

PRINCETON

WELL 2

Lab No.: 9904637 OFF

Lab No.: 9904637 no sample Canceled 6-30-99 SH

PROTIVIN

WELL 1

Lab No.: 9905015 Mike Pecinovsky 7-6-99.

WELL 2

Lab No.: 9905016 Mike Pecinovsky 7-6-99.

RIDGEWAY

2nd Quarter 1999 Page 16 of 19

Lab No.: 9907332 PO #811897443155

WELL 2

Lab No.: 9907333 PO #811897443155

ROCKFORD

WELL 1

Lab No.: 9904243 on the labels 08:45.

Lab No.: 9904243 West Well

WELL 2

Lab No.: 9904244 on the labels 09:15.

Lab No.: 9904244 East Well

ROLFE

WELL 1

Lab No.: 9905245 306 Walnut street

WELL 2

Lab No.: 9905246 Well 3 sample was taken at well 2 by client.

Lab No.: 9905246 Rolfe water plant

ROWAN

WELL 1

Lab No.: 9905260 Pump House

SHEFFIELD

WELL 3

Lab No.: 9904824 no sample Cancel 7-1-99 SH

Lab No.: 9904824 Well 3 is not in service, no pump in well.

SHELLSBURG

WELL 2

Lab No.: 9905739 This well is not available at this time. It has been disconnected

Lab No.: 9905739 no sample Canceled 7-20-99 SH

Lab No.: 9905739 Do not anticipate it being hooked up for at least 2 months.

SOLON LAKEVIEW KNOLLS

WELL 1

Lab No.: 9904106 The vials were received empty.

ST ANSGAR

WELL 2

Lab No.: 9905275 sink

STRUBLE

WELL D-1

Lab No.: 9904370 The paperwork shows the PWS #8447098; per the client #8400733.

WELL D-2

Lab No.: 9904371 The paperwork shows the PWS #8447098;per the client #8400733.

WELL S-1

Lab No.: 9904372 The paperwork shows the PWS #8447098;per the client #8400733.

WELL S-2

Lab No.: 9904373 The paperwork shows the PWS #8447098; per the client #8400733.

2nd Quarter 1999 Page 17 of 19

WELL S-4

Lab No.: 9904575 no sample Cancel 6-28-99 SH

Lab No.: 9904575 We have never had a S-4 well. We did have a S-1 well that was plugged

Lab No.: 9904575 in 1989 and dug a new well S-1 well 30 ft. south of the old one.

TAMA

WELL 3

Lab No.: 9903627 Raw

Lab No.: 9903627 Vials have separate times. 08:19,08:21,08:23.

WELL 4

Lab No.: 9903628 Raw

Lab No.: 9903628 Vials have separate times. 08:09,08:12,08:14.

WFII 5

Lab No.: 9903629 Raw

Lab No.: 9903629 Vials have separate times. 07:56,08:02,08:04.

UNION

WELL 3

Lab No.: 9905432 Client collected from well 3 instead of well 2.

VINCENT

WELL 1

Lab No.: 9905425 Client sampled well 1 instead of well 3.

Lab No.: 9905425 Cancelled BEDDIESW due to TEH sample lost during sample prep.

Lab No.: 9905425 sm 07/22/99

Lab No.: 9906244 Client sampled well 1 instead of well 3.

VINTON

WELL 2

Lab No.: 9905081 Well 2 is not on line right now, we have it capped off and no power

Lab No.: 9905081 no sample Canceled 7-12-99 SH

Lab No.: 9905081 to it. But we should have it back on line around 11-30-99.

WATERLOO

WELL 18

Lab No.: 9903611 Received quart sample jar broken.

WELL 22

Lab No.: 9903613 Received the quart sample jar broken. SH 6-9-99

WELL 7

Lab No.: 9903631 Goes with file 9903604-14

Lab No.: 9903631 duplicate results per Sarah May. 6-24-99 KLP

WAUCOMA

WELL 1

Lab No.: 9904359 Waucoma Water Supply Well

WAUKON

WELL 2

Lab No.: 9905403 819 Allamakee

WELL 3

Lab No.: 9905404 819 Allamakee

2nd Quarter 1999 Page 18 of 19

WELL 4

Lab No.: 9905405 819 Allamakee

WAVERLY

WELL 1

Lab No.: 9904576 no sample Canceled 6-28-99 SH

Lab No.: 9904576 Capped august 1997.

WELL 2

Lab No.: 9904577 Capped august 1997.

Lab No.: 9904577 no sample Canceled 6-28-99 SH

WELL 3

Lab No.: 9904578 Capped August 1997.

Lab No.: 9904578 no sample Canceled 6-28-99 SH

Lab No.: 9904578 Will start digging new well 8 in July 5, 1999. Location on map

WELL 5

Lab No.: 9904379 300 16th Street SW

WELL 6

Lab No.: 9904380 1714 2nd Avenue NW

WELL 7

Lab No.: 9904381 2500 East Bremer Avenue

WEBSTER CITY

WELL 1

Lab No.: 9904241 no sample Canceled 6-28-99 SH

Lab No.: 9904241 Well 1 is out of service. Abandoned and plugged on 8-8-95.

WELL 5

Lab No.: 9904242 no sample Canceled 6-28-99 SH

Lab No.: 9904242 Well 5 is out of service. Well is going to be recased.

WELL 6

Lab No.: 9904239 6-21-99 @ 9:05.

WELLMAN

WELL 2

Lab No.: 9904818 Shallow well

WEST BEND

WELL 1

Lab No.: 9905447 Well 1 was sampled instead of well 2.

WELL 5

Lab No.: 9905449 Well 5 was sampled instead of well 4.

WEST BURLINGTON

WELL 4

Lab No.: 9903685 119 so Gear

Lab No.: 9903685 PO #12351 Testing paid for by UST Fund.

WELL 5

Lab No.: 9903687 no sample Canceled 6-10-99 SH Lab No.: 9903687 Well 5 is inoperable at this time.

WEST LIBERTY

2nd Quarter 1999 Page 19 of 19

Lab No.: 9904019 Power house

WELL 3

Lab No.: 9904020 Water plant

WELL 4

Lab No.: 9904021 Water plant

WEST UNION

WELL 1

Lab No.: 9905014 no sample Canceled 7-12-99 SH

Lab No.: 9905014 #1 well Plugged 12/18/91

WELL 2

Lab No.: 9905013 #2 well Plugged 9/24/99

Lab No.: 9905013 no sample Canceled 7-12-99 SH

WELL 3

Lab No.: 9905008 East Well Head

WELL 4

Lab No.: 9905009 West Well Head

WELL 5

Lab No.: 9905012 #5 local well (out of service)
Lab No.: 9905012 no sample Canceled 7-12-99 SH

WELL 6

Lab No.: 9905010 Fairground Well Head

WESTFIELD

WELL 1

Lab No.: 9904598 no sample Canceled 6-30-99 SH

Lab No.: 9904598 Well #1 was plugged on November 10, 1994.

WELL 2

Lab No.: 9904597 Well #2 was plugged on November 10, 1994.

Lab No.: 9904597 no sample Canceled 6-30-99 SH

WHEATLAND

WELL 2

Lab No.: 9903397 Pump House

WORTHINGTON

WELL 1

Lab No.: 9905310 ms/msd